

SHIP SEP 1

Work Order ID 51363

August 20, 2009 10:36:23 AM



Item ID: D209-669-013

Accept



Setup Start



Revision ID: B

Item Name: Skidtube LH

Stop



Start Date: 08/20/2009 Start Qty: 1.00



Cust Item ID:

Required Date: 08/31/2009 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: mf Date: 09-08-20 Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D209-669-013	Rev B
DSI 9450	Rev A

100 0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPP d209-669-013 CHG003

509/09/07

110 0.00



Pick Kit


Memo

0.00

Packaging

Packaging

10/9/3 (1)



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

August 20, 2009 10:36:22 AM

Page 1

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH


Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D209-669-043RevB  Replacement Skidtube		Manufactured	No			110	Each	3.0000	1.0000			

51357 SL

Warehouse
Location

Loc Qty

Loc Code

Premier

Mezz

3

22797

1

39205

1

39206

1

D2917-1RevB

Manufactured

No

110

Each

0.0000

2.0000

Saddle LH

D2918-1RevB

Manufactured

No

110

Each

3.0000

2.0000

Saddle LH

Warehouse

Location

Loc Qty

Loc Code

Main Warehouse

ST

3

43755

3

51327

B51327 P49/9/9 ①

P49/9/9 ①

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

August 20, 2009 10:36:22 AM

Page 2

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH


Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN4-51A  Bolt		Purchased	No			110	Each	316.0000	8.0000			

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST 316

110328 2

111635 214

112314 100

D2570RevB



Bushing

Manufactured No

110 Each 475.0000 24.0000

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST 67

47246 67

Main Warehouse

ST36 408

50046 190

50356 218

August 20, 2009 10:36:22 AM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

August 20, 2009 10:36:22 AM

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH


Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
MS21042L4  Nut		Purchased	No			110	Each	9,132.000	24.0000 ✓			

08/19/3 ①

Warehouse
Location

Loc Qty

Loc Code

Main Warehouse

ST	9132	
107499	5	
110507	1090	
111827	5996	
112314	2000	
15924	0	
8182	41	

M110507

AN5-36A



Bolt

Purchased

No

110

Each

651.0000

4.0000 ✓

08/19/3 ①

Warehouse
Location

Loc Qty

Loc Code

Main Warehouse

ST	651	
109545	11	
110467	7	
110731	4	
112243	79	
112314	500	
112385	50	

M112243

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

August 20, 2009 10:36:22 AM

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH


Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
S AN960JD516  Washer		Purchased	No			110	Each	1,554.000	8.0000			

09/9/3

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST	1554	
100564	2	
106167	6	
107534	34	
107959	43	
108246	46	
108672	2	
109059	49	
109752	22	
110363	46	
110523	57	
111279	44	
112082	703	
112314	500	

7/12082

MS21042L5



Nut

Purchased

No

110

Each

1,510.000 4.0000



09/9/3 (1)

Warehouse Loc Qty Loc Code
Location

Main Warehouse

ST	1510	
110382	10	
111636	500	
112314	1000	

7/11636

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

August 20, 2009 10:36:22 AM

Page 5

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH


Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
S AN4-7A  Bolt		Purchased	No			110	Each	179.0000	16.0000	✓		

CC 9/2/3

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST	179	
111668	79	
112314	50	
112385	50	

111668

S AN960JD416

Purchased

No

110

Each

10,196.00

32.0000

✓



Washer

CC 9/2/3

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST	10196	
102929	2	
105906	4	
107321	23	
107939	114	
108161	553	
108827	31	
109249	69	
110523	340	
111279	101	
111916	4072	
112314	4887	
16941	0	

111916

August 20, 2009 10:36:22 AM

Shop Packet Print

Page 5

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 6

August 20, 2009 10:36:22 AM

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH


Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2929RevB  Spacer		Manufactured	No			110	Each	23.0000	2.0000	✓		8/29/09

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST

23

43376

23

D2930RevB

Manufactured

No

110

Each

19.0000

2.0000

43376

8/29/09

Spacer

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST

19

43378

19

43378

8/29/09 (1)

D3405-041RevB

Manufactured

No

110

Each

7.0000

1.0000

43378

8/29/09 (1)

Lug Assembly

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST

7

47427

7

50784

August 20, 2009 10:36:22 AM

Shop Packet Print

Page 6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 7

August 20, 2009 10:36:22 AM

Work Order ID: 51363



Parent Item: D209-669-013RevB



Parent Item Name: Skidtube LH

Start Date: 08/20/2009

Required Date: 08/31/2009

Comments:

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
8 AN4C47A 		Purchased	No			110	Each	86.0000	4.0000			
Bolt												

8/29/09 (1)

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST 86

110847 4

111635 32

112431 50

M112431

5 MS21043-4:



Nut

Purchased

No

110

Each

1,254.000

5.0000



8/29/09 (1)

Warehouse Loc Qty Loc Code

Location

OFFSHORE

FG 40

104603 40

Main Warehouse

ST 1214

111819 48

112243 166

112314 1000

M112243

August 20, 2009 10:36:22 AM

Shop Packet Print

Page 7

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 8

August 20, 2009 10:36:22 AM

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH

Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	--------------------------	---------------	----------------	--------

S D3405-043RevB Manufactured No



Lug Assembly

110 Each 8.0000 1.0000



8/27/12 ①

Warehouse Location	Loc Qty	Loc Code
-----------------------	---------	----------

Main Warehouse

ST 8

46589 1

46863 1

47308 4

47856 2

5/205

S D3407-041RevE Manufactured No



Tow Ring

110 Each 18.0000 1.0000



8/27/12 ①

Warehouse Location	Loc Qty	Loc Code
-----------------------	---------	----------

OFFSHORE

FG 3

35780 3

Main Warehouse

ST 5

48356 5

Main Warehouse

ST464 10

50106 10

B 5/659

August 20, 2009 10:36:22 AM

Shop Packet Print

Page 8

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 9

August 20, 2009 10:36:22 AM

Work Order ID: 51363

Parent Item: D209-669-013RevB

Parent Item Name: Skidtube LH

Comments:

Start Date: 08/20/2009

Required Date: 08/31/2009

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3456-1RevA Washer		Manufactured	No			110	Each	49.0000	1.0000			

<u>Warehouse</u>	<u>Loc Qty</u>	<u>Loc Code</u>
<u>Location</u>		
OFFSHORE		
FG	7	
25701	7	
Main Warehouse		
ST	42	
46752	42	

D3417-5RevE

Manufactured No



Washer

110 Each 0.0000 2.0000



✓ 46752
B 31649 1x P 9/9/09 (1)
B 503661x

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

4.0 WEIGHT AND BALANCE

The following weight and balance information is for the replacement Dart parts. The weight and balance of the skidtubes that are being removed from the aircraft is the responsibility of the installer.

Installation	Weight	LONGITUDINAL	
		Arm	Moment
D209-669-011/-012	49.6 lb	170.4 in	8452 in lb
SKIDTUBE INSTALLATION	22.5 kg	4.33 m	97.4 m kg
D209-669-013/-014	43.8 lb	176.5 in	7731 in lb
SKIDTUBE INSTALLATION	19.9 kg	4.48 m	89.2 m kg

5.0 PARTS LIST

Item	Qty -011	Qty -012	Qty -013	Qty -014	Qty -041	Qty -043	Part Number	Description
	X						D209-669-011	SKIDTUBE INSTALLATION, LH (AH-1W/J)
		X					D209-669-012	SKIDTUBE INSTALLATION, RH (AH-1W/J)
			X				D209-669-013	SKIDTUBE INSTALLATION, LH (AH-1P/F/S)
				X			D209-669-014	SKIDTUBE INSTALLATION, RH (AH-1P/F/S)
	1	1			X		D209-669-041	REPLACEMENT SKIDTUBE (AH-1W/J)
			1	1		X	D209-669-043	REPLACEMENT SKIDTUBE (AH-1P/F/S)
1A					1		D2906-041	SKIDTUBE ASSEMBLY
1B						1	D2906-043	SKIDTUBE ASSEMBLY
2	1		2				D2917-1	OUTER SADDLE (FWD, LH)
3		1		2			D2917-2	OUTER SADDLE (FWD, RH)
4	1		2				D2918-1	INNER SADDLE (FWD, LH)
5		1		2			D2918-2	INNER SADDLE (FWD, RH)
6	1						D2919-1	OUTER SADDLE (AFT, LH)
7		1					D2919-2	OUTER SADDLE (AFT, RH)
8	1						D2920-1	INNER SADDLE (AFT, LH)
9		1					D2920-2	INNER SADDLE (AFT, RH)
10	8	8	8	8			AN4-51A	BOLT
11	16	16	16	16			D2570	BUSHINGS
12	8	8	8	8			MS21042L4	NUT (OR MS21042-4)
13	2	2	4	4			AN5-36A	BOLT
14	2	2					AN5-41A	BOLT
15	8	8	8	8			AN960JD516	WASHER
16	4	4	4	4			MS21042L5	NUT (OR MS21042-5)
17	16	16	16	16			AN4-7A	BOLT
18	32	32	32	32			AN960JD416	WASHER
19	16	16	16	16			MS21042L4	NUT (OR MS21042-4)

CONTINUED ON NEXT PAGE

• COPYRIGHT © 2004 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: B

Date: 07.08.23

5/26/23

CONTINUED FROM PREVIOUS PAGE

20	2	2	2	2			D2929	SPACER
21	2	2	2	2			D2930	SPACER
*30A					1	1	D3564-9	WEARSHOE (REPLACES D2577-1)
*30B					1	1	D3566-1	GASKET
*31A					1		D3564-15	WEARSHOE (REPLACES 18" D2577-5)
*31B					1		D3566-15	GASKET
*32A					1	1	D3564-11	WEARSHOE (REPLACES D2577-3)
*32B					1	1	D3566-1	GASKET
*33A					1	1	D3564-5	WEARSHOE (REPLACES D2577-5)
*33B					1	1	D3566-5	GASKET
*34					50	44	AN3C4A	BOLT (REPLACES AN3-4A)
*35					50	44	AN960C10L	WASHER (REPLACES AN960JD10L)
*36					50	44	AKS7-1032-130	INSERT (OR ALS7-1032-130, OR ALS4-1032-130, OR AKS4-1032-130)
*37					12	14	D2594-1	PLUG
*38					12	14	D2594-3	O-RING
*40					2	2	D2855	AFT CAP
*41					4	4	AN3-5A	BOLT
*42					4	4	AN960JD10L	WASHER
*43					4	4	AKS7-1032-225	INSERT (OR ALS7-1032-225, OR ALS4-1032-225, OR AKS4-1032-225)
50	4	4	1	1			D2736-1	GHW LUG
51	8	8	4	4			AN4-46A	BOLT
52	16	16	8	8			D2570	BUSHING
53	8	8	4	4			MS21042L4	NUT (OR MS21042-4)
54			1	1			D2736-3	LUG ASSEMBLY
60	1	1	1	1			D2968-041	TOW RING
61	1	1	1	1			AN970-4	WASHER
62	1	1	1	1			MS21042L4	NUT (OR MS21042-4)

* DENOTES THAT PART IS INCLUDED WITH D2906-041/-043 SKIDTUBE ASSEMBLY

• COPYRIGHT © 2004 BY DART AEROSPACE LTD •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: B

Date: 07.08.23

513023

REFERENCE ONLY

5.0 PARTS LIST

ITEM	QTY -011	QTY -012	QTY -013	QTY -014	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
	X						D209-669-011	SKIDTUBE INSTALLATION, LH (AH-1W/J)
		X					D209-669-012	SKIDTUBE INSTALLATION, RH (AH-1W/J)
			X				D209-669-013	SKIDTUBE INSTALLATION, LH (AH-1P/F/S)
				X			D209-669-014	SKIDTUBE INSTALLATION, RH (AH-1P/F/S)
	1	1			X		D209-669-041	REPLACEMENT SKIDTUBE (AH-1W/J)
			1	1		X	D209-669-043	REPLACEMENT SKIDTUBE (AH-1P/F/S)

IS:

50	4	4	1	1			D3405-041	LUG ASSEMBLY
51	8	8	4	4			AN4C47A	BOLT
52	16	16	8	8			D2570	BUSHING
53	8	8	4	4			MS21043-4	NUT
54			1	1			D3405-043	LUG ASSEMBLY
60	1	1	1	1			D3407-041	TOW RING ASSEMBLY
61	1	1	1	1			D3456-1	WASHER
62	1	1	1	1			MS21043-4	NUT
63	2	2	2	2			D3417-5	WASHER

WAS:

50	4	4	1	1			D2736-1	GHW LUG
51	8	8	4	4			AN4-46A	BOLT
52	16	16	8	8			D2570	BUSHING
53	8	8	4	4			MS21042L4	NUT (OR MS21042-4)
54			1	1			D2736-3	GHW LUG
60	1	1	1	1			D2968-041	TOW RING
61	1	1	1	1			AN970-4	WASHER
62	1	1	1	1			MS21042L4	NUT (OR MS21042-4)

51363

DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. A
MFG. APPR.	N/A	DSI 9450	SHEET 2 OF 3
APPROVED		TITLE	SCALE
DE APPR.		SKIDTUBE INSTALLATIONS	NTS
DATE	09.02.24	COPYRIGHT © 2009 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR DISCLOSED TO ANY OTHER PERSON OR ENTITY WITHOUT THE WRITTEN PERMISSION OF DART AEROSPACE LTD.	